


HOUGHTON
COUNTY


BARAGA
COUNTY

Surface Condition (PASER Rating)

	Structural Improvements (1 - 4) 171.279 miles, 64%
	Capital Preventative Maintenance (5 - 7) 83.659 miles, 31%
	Routine Maintenance (8 - 10) 13.944 miles, 5.1%



VILAS COUNTY,
WISCONSIN



FLORENCE COUNTY,
WISCONSIN



IRON COUNTY
Asset Management
Surface Rating of Federal Aid Road
2015-2016