


HOUGHTON COUNTY


BARAGA COUNTY

Surface Condition (PASER Rating)

—	Structural Improvements (1 - 4) 112.48 miles, 47%
—	Capital Preventative Maintenance (5 - 7) 92.392 miles, 38%
—	Routine Maintenance (8 - 10) 36.146 miles, 15%



VILAS COUNTY, WISCONSIN



IRON COUNTY
Asset Management
Surface Rating of Federal Aid Road
2016-2017

FLORENCE COUNTY, WISCONSIN