


HOUGHTON COUNTY


BARAGA COUNTY

Surface Condition (PASER Rating)

—	Structural Improvements (1 - 4) 103.852 miles, 39%
—	Capital Preventative Maintenance (5 - 7) 106.789 miles, 39%
—	Routine Maintenance (8 - 10) 58.848 miles, 22%



VILAS COUNTY, WISCONSIN



IRON COUNTY
Asset Management
Surface Rating of Federal Aid Road
2017-2018

FLORENCE COUNTY, WISCONSIN